



PLAN VIEW

STATION	DESCRIPTION
1	PARCK/LOAD
2	ALKALINE CLEAN (316 S/S)
3	SPRAY RINSE
4	OVERFLOW RINSE
5	ACID ETCH
6	SPRAY RINSE
7	OVERFLOW RINSE
8	DESMUT (316 S/S)
9	SPRAY RINSE
10	OVERFLOW RINSE
11	ZINCATE-1
12	SPRAY RINSE
13	OVERFLOW RINSE
14	NITRIC ACID 50% (316 S/S)
15	SPRAY RINSE
16	OVERFLOW RINSE
17	ZINCATE-2
18	SPRAY RINSE
19	OVERFLOW RINSE
20	ELECTROLESS NICKEL (316 S/S INNER TANK)
21	ELECTROLESS NICKEL (304 S/S OUTER TANK)
22	ELECTROLESS NICKEL (304 S/S OUTER SHELL)
23	ELECTROLESS NICKEL
24	ELECTROLESS NICKEL
25	ELECTROLESS NICKEL
26	ELECTROLESS NICKEL
27	ELECTROLESS NICKEL
28	SPRAY RINSE
29	OVERFLOW RINSE
30	HOT RINSE (316 S/S)
31	DRYER (304 S/S)
32	UNLOAD/PARK